



NOTES-

THIS DWG 286 506A PULLEY INSTALL  
REPLACES 286 1033 PULLEY INSTALL  
FOR F8Y-5 AIRPLANES AS NOTED BELOW

SEE 286 1033 FOR INSTALLATION  
DETAILS NOT SHOWN ON THIS DWG

DRILL #10(193) FOR AN3 BOLTS



H 442

[illegible]